

Answer on question # 55423, Physics / Electric Circuits

Question The ratio of the rms value of AC components to the DC value of load voltage is referred to as the
Voltage Regulation
Form Factor
Ripple Factor
Rectification Factor

Solution The ratio of the rms value of AC components to the DC value of load voltage is referred to as the Form Factor.

<http://www.AssignmentExpert.com/>